

(6) GENERALLY GOOD - SEE REMARKS.

(5) GOOD

G. TAKE RECEIVED 15/2000Z APR IN COVERED STEEL BOXES. NO TRACKER FILM RECEIVED. TWO MANUFACTURER'S SPLICES EACH SIDE. ERRATIC METERING ON FOLLOWING FRAMES:

2931/2932L - 1/4 INCH

2931/2932R - 7/16 INCH

2932/2933L - 1/2 INCH

2932/2933R - 7/16 INCH

SECRET

GROUP 1 Encluded from automatic downgrading and declassification 1095 (IN--73811)

SECRET

PAGE TWO

2933/2934L - 3/8 INCH 2933/2934R - 5/16 INCH
2934/2935L - 5/8 INCH 2934/2935R - 1/2 INCH
INTERMITTENT LIGHT PRESSURE MARKS OR STATIC THROUGHOUT LEFT SIDE.
PATTERN CONSISTS OF BROKEN LINE OF SMALL SPOTS OF HEAVIER DENSITY
THAN SURROUNDING AREA. SIZE OF SPOTS VARIES FROM 1/8 INCH TO 1/4
INCH IN DIAMETER. LOCATION OF LINE APPROXIMATELY THREE INCHES FROM
TITLED EDGE. SAME PATTERN HAS BEEN APPARENT AND REPORTED ON SOME
PREVIOUS MISSIONS. DEFECT DOES NOT SERIOUSLY DEGRADE FILM. DATA
SHEET INDICATED "B" CAMERA WAS IN MODE I CONFIGURATION, HOWEVER,
3L AR POSITIONS WERE NOT OPERATIONAL. TAKE WAS THEREFORE TITLED IN
CONSECUTIVE NUMERICAL SEQUENCE WITH FRAME 0001 CORRESPONDING TO
DATA CHAMBER NUMBER 0001.

END OF MESSAGE